

:: ACRYLIC 1-K WG TOPCOAT CLEAR MATT

Description:

Is a 1-component solvent-free acrylic polymer that dries quickly and can be walked on quickly. This sealing layer provides an ultra matt, scratch-resistant, UV-resistant protective layer that adheres well to most surfaces. Is particularly suitable for finishing the Flexo cast floor. Can also be used as parquet varnish.

Available in 0.5 l – 1 l – 2.5 l – 5 l and 20 l packages.

Application:

For finishing both the 2 K PUR Flexo casting floor and the Perfect Mineral Deco. Provides the surface with improved UV resistance, hardness and scratch resistance. The coating is easy to apply, very wear and scratch resistant, makes it dust-free and provides an easy-to-maintain surface. Very good chemical resistance and equipped with UV filters. When using a roll, a light anti-slip structure (orange peel) remains.

Data upon delivery:

Color:	milky white
Viscosity:	4000 - 6000 mPas
Specific gravity:	approx. 1.05 g/cm ³
Shelf life:	12 months in closed packaging
Consistency:	thin liquid

Technical data:

Consumption:	200 gr/m ²
Shore:	Not applicable

Processing:

Always ensure that the surface is as dry and grease-free as possible and apply the layer with a suitable fur roller. Do not open the can until the material contained therein is actually going to be processed.

Once opened, process packages as completely as possible.

Thoroughly mix the coating in advance to a homogeneous mass. Spread the layer with a 25 cm nylon roller both vertically and horizontally and then roll again vertically. Within 5 minutes, the coating should be rolled vertically again with a dry nylon roller that is as wide as possible. Apply the coating with a maximum of 200 gr/m², as a higher consumption can cause foaming. Always use nylon rollers and make sure they are new and well wetted with the coating. A next layer can be applied after 3-4 hours, with a maximum of 24 hours, because then you first have to roughen up slightly mechanically. Maximum number of layers: 3 Minimum processing temperature 5°C and maximum: 30°C. Dust dry after 40-45 min. Please note: once opened packages must always be sealed airtight to prevent further hardening in the can.

Safety:

Always wear appropriate protective clothing and gloves. Avoid prolonged skin contact.

Cleaning agent for tools: water and soap. Provide adequate ventilation.

The information on this page is technical guidance and has been compiled to the best of our knowledge.
However, it never gives rise to any liability on our part.